SOUTHERN DISTRICT OF NEW Y	ORK	
SIXTEEN THIRTEEN MARINE S.A.	·,	x 08 CV 1318 (HB)
	Plaintiff,	ECF CASE
-against-		
CONGENTRA AG,		
	Defendant.	x

### **Declaration of Konstantin Petrunin**

### I, Konstantin Petrunin, BEING DULY SWORN DEPOSES AND SAYS:

- 1 I was involved in operating the m/v Nicholas M during her time charter trip to St. Petersburg for Congentra AG of 6301 Bahnhofstrasse 12, Zug, Switzerland.
- I am authorised by Congentra AG, the Defendant, to make this Declaration on their behalf.
- There is now produced and shown to me a bundle of true copy documents marked "KP1" where numbers appear in square brackets during the course of this Declaration there are references to page numbers in the bundle.
- 4 I read, write and speak English.
- I have read the Declaration of Edward Eurof Lloyd-Lewis and can confirm that the contents of paragraphs 5 to 12 are correct. For ease of reference I adopt the same definitions as those in the declaration of Edward Eurof Lloyd-Lewis.
- Following the information from the agent Anteks that the cargo was likely to be wet damaged, SGS, an internationally recognised surveying company, was requested by Euroweg Zerno to inform them regarding the condition and quantity of the damaged cargo. On 3 December, 2007 they issued a Letter of Reserve to the Vessel in which they stated that the whole surface of the Cargo in hold no. 4

6016603

Kly

was found to be wet and there was mould along the perimeter. According to SGS the Cargo had strong musty smell and yellow brown colour, the wetting went down to about 1 metre and that the Cargo was wet, musty and found to have an abnormal temperature [pg. 1].

- 7 Discharge of undamaged Cargo from hold no. 5 commenced as per Master's message at 02:25 hours on 3 December 2007 following completion of customs formalities and an improvement in weather conditions [pg 2].
- 8 On 3 December 2007, the Marinex-ILCS surveyor, Alexey Zagumennyy appointed by AXA Corporate Solutions Cargo Underwriters presented a Letter of Protest to the Owners and Master with regard to the presence of wet and mould damaged Cargo in the middle and corners of hold no. 4. The Letter of Protest went on to state that the total quantity of damaged Cargo would be determined in the course of discharge [pg 3]
- 9 On 3 December 2007, Wakefield Inspection Services (Russia) ("Wakefield"), who had been appointed by the American P&I Club ("Owners' Club") took samples of the damaged Cargo in hold no. 4.
- 10 Subsequently, Wakefield issued Sampling Statement Number 1 dated 3 December 2007 [pg 4]. This document wrongly recorded that Anteks was Euroweg Zerno's representative for the purpose of taking samples. The same day Congentra and Euroweg Zerno wrote to Wakefield to ask that these errors be corrected and they reserved their rights as to the binding nature of the sampling exercise [pg 4A]. In addition, the following information was requested:
  - 10.1 How the samples had been drawn and the methodology employed to ensure that they were representative of the damaged portion of the Cargo. For example, was the GAFTA 124 sampling regime employed.
  - 10.2 The current whereabouts of each sample drawn.
  - 10.3 The contact details of the laboratory where the samples were sent and the likely time-line for the publication of the results of their analysis.

6016603

- Owners' proposals for sorting sound from damaged Cargo so that Cargo Interests could determine the damaged quantity. In this regard, there was an issue as to whether the Russian Authorities would permit the landing of damaged Cargo which would have had an impact on Cargo Interests and damages claimed.
- 11 Whilst Wakefield acknowledged receipt of our message on 4 December [pg 5] and stated that they would amend Sampling Statement No. 1 I do not believe we have ever received the amended document. Wakefield also refused when pressed, to disclose the identity of the laboratory which was analysing the samples without the consent of Owners' Club [pg 6]. Neither we, Euroweg Zerno, Cargo Interests' Surveyors or BLG have ever received any information from Wakefield and/or Owners as to which laboratory was used to analyse these samples. Nor have they revealed testing protocols. All Owners have done through their lawyers is assert that the Cargo was wetted by fresh water thus indicating that the damage was caused pre-shipment.
- The Russian authorities condemned the damaged cargo in hold no.4 prohibiting its discharge unless it was for destruction.
- On 6 December 2007, BLG wrote to Owners and their managers, Chian Spirit Maritime Enterprises Inc via brokers Billmar Chartering to inform them *inter alia* that SGS was to oversee the discharge and segregation operation for Cargo Interests.
- On 15 December 2007 special trucks for transporting waste arrived at the Vessel to transport the wet damaged Cargo for destruction as required by the Russian Authorities. SGS also attended the Vessel in order to take samples of the damaged Cargo and to supervise the segregation operation. Segregation of the Cargo had to take place on board the Vessel as there were no suitable storage facilities for soybeanmeal ashore.
- At 11:00 a.m. on 15 December 2007, Sergey Stefansky, an Inspector with SGS arrived on board the Vessel.

6016603

KM

3

- Mr Stefansky attempted to give a letter confirming his appointment to the Master. The Master however refused to accept the letter and then denied him access to the hold. Mr Stefansky was therefore not able to do his job as he required access to the hold.
- Upon information and belief, the discharge of soybeanmeal in St. Petersburg is usually effected into railway wagons, but not into trucks. However, since the discharge of the damaged cargo ex. hold no. 4 to customers by railway wagons was impossible due to prohibition of Russian Authorities, Euroweg Zerno had to discharge the damaged cargo into trucks to transport the cargo for destruction. Special trucks from OOO Profimpex permitted to perform destruction were ordered. But as a consequence of the Master's refusal to permit access to the hold the trucks were kept waiting all day whilst BLG and Owners' Club negotiated access.
- Eventually at about 19:30 local time, the trucks having waited most of the day left empty.
- Notwithstanding the fact that discharge of hold no. 4 could not commence, discharging of hold no. 1 continued and was completed that day and discharge also took place from hold no. 6. The same day, however, wet Cargo was also found in hold no. 2. Accordingly, discharge of the damaged cargo from hold no. 2 was prohibited by the Russian authorities except for destruction.
- 20 On 16 December 2007, discharge continued from hold no. 6.
- On 18 December 2007, the SGS Inspector returned to the Vessel following lengthy negotiations between BLG and Owners' Club with regard to access. It had been necessary for Cargo Interests to threaten proceedings before the English Court. However, when the inspector re-attended the Master once again refused him access. Eventually, at 22.10 hours local time, the Master granted permission to the SGS Inspector access to the holds.
- 22 Discharge continued until 28 December 2007.

6016603

My 4

Filed 03/05/2008

- 23 I understand that Owners have alleged that Cargo Interests in bad faith refused throughout to discharge the Cargo and to segregate it as to good and damaged ashore, thereby extensively delaying the Vessel from completing her discharge operations. This is completely untrue. As I have stated in paragraph 14 above there is no on-shore storage facilities in the port of St Petersburg where soyabeanmeal can be sorted. Furthermore, I understand that the Master has actually stated in his comments to the Statement of Facts that despite the fact that the commencement of discharge from hold nos. 2 and 4 was delayed discharging progress and the overall discharging time was not affected [pg 7 - 8]. I therefore do not understand how Owners can now make such an allegation.
- . 24 On 28 December 2007, BLG made a request to Owners' Club for permission for surveyors from Marinex and SGS to conduct an ultrasonic test on the hatch covers of hold nos. 2 and 4. When the SGS surveyor attended the Vessel on the evening of 28 December he was however refused access to the holds by the Master. Notwithstanding the Master's refusal it was decided not to pursue the matter further by making an application to the English Court because Congentra wanted to re-deliver the Vessel.
- 25 At about 20:30 local time, we were informed by Mr Drozdov, the SGS surveyor, that the ship's class certificates had been withdrawn because of a problem with hatch cover no. 6, and the crew being under strength. Later that evening, we also received a message from the Master [pg.9] to say that the Vessel had to wait for the weather to improve so that the pilot who would shift the Vessel to anchorage could be dropped off safely. Accordingly, the Vessel's sailing and re-delivery would be delayed. The Master's message made no mention of the fact BV had withdrawn the Vessel's certificates and therefore could not sail.
- On the morning of 29 December Congentra protested to the Master with regard to 26 the delay in the Vessel sailing after it had given instructions for re-delivery [pg 10]. To our surprise however, the next thing we heard was that the Vessel was being inspected by St Petersburg Port State Control and was detained at 15:30 hours local time. At the time we were informed that Port State Control had detained the Vessel because the Cargo Ship Safety Construction Certificate and the Class

6016603

Certificates had been withdrawn. We also understood that the Vessel did not have its full complement of crew [pg 11-20].

- 27 I understand that Owners are alleging before this Court that Congentra, Euroweg Zerno and Anteks persuaded Port State Control Officials to go on board and detain the ship for a number of days in an attempt to gather evidence against the Vessel. This is absolute nonsense and I can categorically deny that there is any truth in this allegation. Prior to the Vessel's detention Congentra had absolutely no contact with Port State Control.
- 28 Following Owners' application to this Court Congentra has made extensive enquiries of a number of organisations in an effort to establish why Port State Control visited the Vessel on 29 December 2007.
- 29 I have spoken with Sergey Fishov, who is the International Transport Workers' Federation's Russian representative. He informed me that whilst the Vessel was in St Petersburg he had received complaints from members of the crew. They complained about the arrangements for their repatriation and health and safety at work issues and according to him 'feared for their lives'. For example, they informed him that there was a problem with the ballasting tank on the Vessel and the bilge pump1. Mr Fishov told me that as a consequence he reported these deficiencies to Port State Control.
- 30 I have also spoken with Anton Chuprina of Nordweg who conducted repairs to the hatch cover of hold no. 6. He informed me that after BV had confiscated the Vessel's certificates, they had visited the Vessel on 29 December in order to examine hold no. 6 and to provide a quotation. However, because of the Russian Christmas and New Year holidays, work could not commence on repairing hatch cover no. 6 until 3 January such works being completed, he informed me, on or about 8 January 2008. This account is corroborated by:
  - The Vessel's Manager's e-mail correspondence with Britannia Bulk, the i) Vessel's next charterers in which they complain that on-shore repairs

6016603

6

- cannot commence any earlier than 3 January 2008 because of the Russian holidays [pg 21-23].
- ii) An e-mail from the Master to the Managers on 7 January informing them that the repairs to the hatch cover are continuing and are not expected to be completed until 8 January [pg 24].
- I have also made enquiries of BV, the Vessel's Classification Society. It is my understanding that they attended the Vessel on 28 December 2007 because when the Vessel had previously been in Maceio, Brazil, a recommendation had been imposed by BV because of the presence of an oil leakage on the hatch covers and the hydraulic cylinders were to repaired and tested. The time limit on this recommendation expired on 28 December 2007 [pg 25]. I assume Owners asked BV to attend the Vessel whilst it was in St Petersburg in order to obtain a time extension for the recommendation but during their visit they discovered that the aft hatch cover on hold no. 6 could not be closed. According to the letter BV left with the Master it was this defect and the impossibility of repairing it prior to the ship's departure which led the BV surveyor to confiscate the Vessel's classification certificate and Cargo Ship's Safety Construction Certificate [pg 26].
- J understand that the Safety of the Life at Sea Convention ("SOLAS"), Chapter 1, Part B, paragraph (c), imposes an obligation on a Classification Society to report the withdrawal of a vessel's Classification Certificate and Cargo Ship Safety Certificate to the local Port State Control [pg 27-32]. Therefore, BV being mindful of its obligations under SOLAS very likely reported its actions to Port State Control.
- Russia is signatory of the Paris Memorandum of Understanding on Port State Control ("the Paris MoU"). The Paris MoU aims to eliminate the operation of substandard ships through a harmonized system of Port State Control. The Maritime Authorities of 25 nations including Canada, France and the UK are parties to the convention.

6016603

The

The PSC report states that bilge collecting tank no. 9 was leaking and thus a ground for detention.

Filed 03/05/2008

34 The Paris MOU sets out a number of criteria which are used to identify vessels which merit the attention of Port State Control and should be subjected to inspection. Section 3.1 of the Memorandum [pg 33] provides *inter alia* that:

"In the absence of valid certificates or documents or if there are clear grounds<sup>2</sup> for believing that the condition of a ship or its equipment, or its crew does not substantially meet the requirements of a relevant instrument<sup>3</sup> a more detailed inspection will be carried out<sup>4</sup>...."

- 35 Examples of 'clear grounds' include [pg 36];
  - Ships which have been the subject of a report or complaint by inter alia a crew member, or any person or organisation with legitimate interest in the safe operation of the ship<sup>5</sup>;
  - ii) Loss of classification certificates<sup>6</sup>.
- The Vessel was therefore an obvious candidate for an overriding priority inspection.
- It is, I believe, highly significant that the reason given by BV to Owners for temporarily withdrawing the Vessel's certificates was the damage to the aft hatch cover of hold no. 6 and the fact that repairs could not be carried out before the Vessel sailed. This particular defect also constituted one of the grounds for the Vessel's detention. This I submit is evidence of the fact that BV and Port State Control were both in agreement as to the seriousness of this defect. It follows that statement in paragraph no. 12 of the Amended Verified Complaint that Russian Port State Control eventually released the Vessel without any serious deficiencies having been found that would warrant detention is entirely false and misleading.

6016603

My "

See Annex 1 Section 4 for examples of 'clear grounds' Section 4.1 Ship has been identified as a priority case for inspection under Section 1.1.

See Paris MoU Section 2 [pg 37-38]

See Paris MoU Section 3.1.

See Annex 1 Section 1.1.4 [pg 34].

See Annex 1 Section 1.1.6 [pg 34].

Filed 03/05/2008

38 It is also entirely false and misleading for Owners to state in their Amended Verified Complaint at paragraph no. 15 that on or about 2 January that it was determined that the Vessel had no problems which justified her detention by Port State Control, and that BV had by this stage returned the Vessel's certificates after the hydraulic system had been repaired prior to 31 December 2007. As is clear from the Master's email of 7 January to the Vessel's managers, BV returned some certificates on 6 January but still retained the Hull annex to certificate of classification and repairs were continuing. Indeed, according to Nordweg were not completed until at least 8 January 2008.

I declare under penalty of perjury and the laws of the United States of America that the foregoing is true and correct.

Executed this 4th day of March 2008, Moscow, Russian Federation.

Signed:

# **EXHIBIT KP-1**

	TEJI:	5 £ 8	2007 15:5 <del>9</del>	다양			
SGS AGRICULTURAL SERVI	ces	WORKING SHEETS DRY PRODUCTS  LETTER OF RESERVE					
		CELLER OF RESERVE		 '			
Order references	ДЕТАЛИ PASOYЫ:						
Order number: Hovep palions:	1229/A-Sp-07	Destination/Origin:	/ Argentina				
Mean of transport	m/v "NICHOLAS M"	— Казна-вона / прсисфукденне: Овъе:					
Транспортные сперевно:	10 A MICHOLOGY ME		03/12/07				
Place/Terminal/Berth;	S-Petersberg, STP-39	Quantity/MT;	30,204,000	<del></del>			
Умето инспекцију Гаривана; "Секцинасти:		Казичество/ ИТ:					
Chys:	Sovebean meat in Bulk	Agent:	ANTEX				
Client/Principal:	EUROWEG ZERNO	Contradictions	<del></del>	<del></del>			
Хімент/Зеканчік;		<u></u>		<del></del>			
Londing/Disclarge: (IOC)/NA/Euroveka:	Discharge	Other parties;					
		Трокые стороны;					
TO: A KONY	MASTER						
CC: /Kanka: CC: /Kanka:	EUROWEG ZERNO			- · <del> · · ·</del>			
CC: /Koms:	ANTEX						
Your ref.:	<del></del>			· · · · · · · · ·			
- 							
h	<del> </del>			<del></del>			
	LETTER OF RE	SERVE / ПИСЬМО РЕЗЕРВ	<b>5</b>				

imment or indicate further investigation may be necessary:

Во время выпрузки вышеуказачного судув жы наблюдали следующую ситуацию, следствивы которой могут быть недостоверные дальные по качеству/количеству, или в результате которой может вознакилуть необходимость последующего EMOUSEYEITSCIES:

On 02/12/07 during the exemination and sampling of the cargo ax the hold No. 4 the whole surface of the cargo was found to be wet. Along the perimeter of the hold it was notices the mould.

The catgo was found to have strong-musty smell and yellow-brown colour. The cargo was checked by grab bucket in the middle of the hold approximately on the depth of 1 meter previously. Thus it was found wet and musty cargo; the cargo has abnormal temperature.

In view of the above, we reserve the right of our principal to severt to this matter should the need arise in fultime. Я соотвействии с этим мы сставляем право за нациен киментом предприниметь дальнейвине действия в случае, если в такрами возникней необходиность,

This letter is issued on behalf of our principals without prejudice to the rights and privileges of any / all parties

мострящих выпульта видели и выпульный и выда здручи сед втерних отвижений то, фермилистий выпульный выпульный в стороны.

SGS Vostok Ltd. СЖС Восток Луд.

TRIFOUND

Acknowledged / Received by Принято к сведению / Сохучено (ком)

BPSYEKO 03.42.07 ARUTAK OT ROBRISEY DYKA3AA CA.

a the Several Conditions (<u>your sgs.com/general</u>).

This fax was received by QFI FAXmaker fax server. For more information, visit; http://www.gfi.som



### "Operations Congentra" <operations@congentra.co m>

02/03/2008 08:21

To "Eurof Lloyd-Lewis" <elloyd-Lewis@blg.co.uk>

G

bcc

Subject IFW: NOON DAILY CARGO REPORT

----Criginal Message----

From: Master NicholasM [mailto:Master.NicholasM&telaurus.net]

Sent: Monday, December 03, 2007 4:04 PM

To: Operations Congentra Cc: operations department

Subject: NOON DAILY CARGO REPORT

FM: MV NICHOLAS M TO: CONGENTRA AG REF: 016/03-DEC-07

NCON DAILY CARGO REPORT 12:00 LT 02-DEC-2007

1. CARGO LOADED FAST 24 MRS: N/A

2 CARGO DISVHARGE PAST 24 HRS: 795.9 MT AS PER SHIP DRAFT SURVEY

3. TOTAL CARGO ONBOARD: 29,408.1 MT

4. BUNKERS ROB: FO/247.32MT DO/50.50MT

5. ETD: 22-DEC WP/AGW

REMARKS:

02-DEC-07 1315 B/L NO. 6 RECEIVED ONBOARD COVERING

CARGO QTY 3,730 MT FOR HOLD NO. 5 AS PRR

YR CONFIRMATION BY PHONE.

03-DRC-07 0225 COMMENCED DISCHARGING IN HOLD NO. 5

0305-0355 STOP DISCHARGING, STEVS BREAK TIME 0730-0840 STP DISCHARGING, STEVS BREAK TIME 1100-1148 STP DISCHARGING STEVS BREAK TIME

BEST REGARDS MASTER FROM : NICHOLASM



O/ref.: Date: 03.12.07 FAX 1900 16,0800009 3820558

-23-DEC 2237 25:237m

International Loss Adjusters, Consultants and Surveyors MARINEX-ILCS Ltd.

> Owners and Master. "NICHOLAS M

### LETTER OF PROTEST

We are, survey bureau MARINEX-RUS Ltd., acting at the appointment and on behalf of the cargo interests involved, did perform inspection of cargo of Meal so bulk delivered on board mp to St. Petersburg.

Wet damage to cargo was noted in the course of inspection of cargo hold No. 4 wet and moulded cargo of Soga bleat in but was found to be located in the middle and in the cournes of the cargo hold not To tal quantity of damaged cargo will be determined in the weerse of discharging

In accordance with the above, in the name of the cargo interests involved and without prejudice to our principal's liability we hereby hold the Carrier liable for any consequential losses of material and/or

Please consider this letter as an official Profest given in due form and way and have your P&I Club surveyor appointed for joint inspection.

Yours faithful?

Alexer EAGIMENNY

Attending surveyor

MARINEX-ILCS Ltd., St.Petersburg

Please acknowledge the receipt of this letter.

Date 03-PER-2007 Time 15:36 H

ACCUMULENCE NECTIFY DALY

Signature



12, Tambovskyya Str., St.Petersburg, 192007, Russia Tel.: (812) 740-1441 Pax: (812) 740-1877 E-mail: office@dcs.m





## ООО «Вэйкфилд Инспекции Сервисис (Раша)»

198035, Санкт-Петербург, ул. Гапсальская, д. 1, оф. 105

	Tert/Caxc: (812) 335 76 35 / 36
	AKT OTEOPA HPOE (OEPASHOB) / SAMPLING STATEMENT No. /
	1. Here cocrashence / Date of issue: C3.42.207 2. Mecro cocrashence / Place of issue: M/V NICHOVASS M. BENTAN 25 3. Ast cocrashen ancherropom / Statement issued by inspector: V. Zakharov 4. Ordop apod oppossement cytacrash opencrashings / The following representative took
2	participation in sampling: 1. Best one PV. rearrescalled ive of Control of Astronomy A A control of Instruction Company.  I agree on a control of the Contro
P	7. Terremoration gonyment Transport document No B/L N/1 Label 18 11.2
	8. Transmorphise spensors of My MISHOLASM 9. Hara corressor/Date of loading 16.11, 2507.
	10. Here no crymneres reseps / Date of goods delivering: 10.1 He craming / morr resussesses / On r. w. station / port destination: Scient Pebershous 10.2 He carea no nyear en n / On repoliver's warehouse
	11. Komprecise / Quantity: 4037,000 MT. 11.1 Metro/pieces
	12. Sen ynakoake / Type of packing: 10 buse.  Harrossunë ari cocrasses a ross, wo / This statement was issued that on 92.42.2007.
	отобраны пробы для / sampling was carried out for Laboratory artalias
	(22 of open and property of the control of the cont
	11. Пробы отобрания в соответствии с / Sampling was carried out in accordance with:
	(приме, могноствение на объе проблам мыстам развидующей проблам маста (размер) в отдельностя / Goods quantity which were taken for samples' making, quantity and weight
	(size) per each sample: 1. Sample: N1 -0.749
	14. Hookin nomentents / Samples placed into Plastic Scarios
	15. Orofipannie profix nampannem / Taken samples were delivered to the profit of the samples were delivered to the samples wer
Y	HIGHERTOP / Inspector:   The act and the resentatives:   The a
	· · · · · · · · · · · · · · · · · · ·

### Operations Congentra

OT.

Operations Congentral

Отправлено: 3 декабря 2007 г. 21:38

Komv:

Billmar Chartering Ltd.

Testa:

FW: Nicholas M

Отменить:

3 декабря 2008 г. 20:18

Pls pass on to the owners:

Dear Sirs

Nicholas M

Voyage - San Lorenzo to St Petersberg Bifl of lading No 1 dated 18 October 2007 Wet damaged cargo - Hold Number 4



We have been sent a copy of Sampling Statement No 1. We write to inform you that the document is in error in that its states that the bill of lading and date of shipment is 18 November 2007. The correct date of shipment and the bill of lading is 18 October 2007, Please correct the document accordingly.

We further note that the Statement records that Bessonov PV attended the sampling together with Owners' and cargo insurers' representatives. The cargo has been consigned to OOO Euroweg Zemo and Mr. Bessenov is not their representative for the purpose of taking samples. In this respect therefore we must expressly reserve our rights as to the binding nature of the sampling exercise. That said however, please provide the following information immediately so that we can consider the same:

- How were the samples drawn and methodology employed to ensure that they are representative of the damaged portion of the cargo, for example, was the GAFTA 124 sampling regime employed?
- The current whereabouts of each sample drawn?
- The contact details of the laboratory to where the samples drawn will be sent and the likely time line for the publication of the results of their analysis.



4. Owners' proposals for sorting sound from damaged cargo so that we can determine the damaged quantity. In this regard there may also be an issues as to whether the Russian authorities may permit the landing of damaged cargo and this may also have an impact on cargo interests' damages claim.

We have just seen Owners' managers, email to their local P & I Club representative. We are very disappointed with the tone of their communication. The cargo has been clearly damaged. This can only have happened as a consequence of a breach of contract and/or duty on Owners' part in the carriage of the cargo. We shall be writing further to Owners and their P & I Club further in this regard shortly.

In the meantime, we must confinue to reserve all our rights.

Yours faithfully

Congentra AG and OOO Euroweg Zerno

YOURS FAITHFULLY. CONGENTRA AG

From: STP-OPERATIONS@wakefieldinspection.com [mailto:STP-OPERATIONS@wakefieldinspection.com]

Sent: Tuesday, December 04, 2007 12:02 PM

To: operations@congentra.com Subject: m/v "Nicholas M", reply

Dear Sirs,

we have the following to say about Your letter of 03/12/2007:

- 1. The samples were drawn in accordance with GAFTA 124 sampling regime.
- 2. The samples were placed into plastic sachets and sealed
- 3. The samples will delivered to independent laboratory. The results of analisis will be sent to You as soon as we receive them.
- The question of sorting sound from damaged cargo is out of our competence.
- 5. Corrected Sampling Statement #1 will be sent soon.

Best regards,

Sieva Zakharov.

Wakefield Inspection Services (Russia) Ltd. apartments 105, 1 Gapsalskaya Street. St. Petersburg, Russia, 198035, tel/fax: +7 812 3357635 / 36 / 37 / 38 www.wakefieldinspection.com



"Operations Congentra" <operations@congentra.co m>

02/03/2008 13:52

To "Eurof Lloyd-Lewis" <elfoyd-Lewis@blg.co.uk>

œ

bcc

Subject FW: m/v "Nicholas M", reply

From: 5TP-MANAGEMENT@wakefieldinspection.com

[mailto:STP-MANAGEMENT@wakefieldinspection.com] On Behalf Of

STP-OPERATIONS@wakefieldinspection.com
Sent: Wednesday, December 05, 2007 3:35 PM

To: Operations Congentra

Subject: RE: m/v "Nicholas M", reply

Dear Sirs,

I could not advise you information about laboratory, I need permission from P&I Club at first,

brgds, Dmitriv

Wakefield Inspection Services (Russia) Ltd. apartments 105, 1 Gapsalskaya Street, St. Petersburg, Russia, 198036, tel/fax: +7 812 3357635 / 36 / 37 / 38 www.wakefieldinspection.com

"Operations" <operations@congentra.com>

TD<\$TR-OPERATIONS@wakefieldinspection.com>

05.12.2007 14:50

CC<office@jlcs.ru>, "Bikmar Chartering Ltd" <chartering@bikmar.gr> SubjectRE: m/v "Nicholas M", repty

TO: WAKEFIELD INSPECTION CC: MARINEX-ILCS; OWNERS OF M/V NICHOLAS M

DEAR SIRS.

THANK YOU FOR YOUR EMAIL OF YESTERDAY.

HOWEVER, YOU OMITTED TO IDENTIFY THE IDENTITY OF THE INDEPENDENT LABORATORY WHICH IS CONDUCTING THE ANALYSIS. PLEASE LET US HAVE THIS INFORMATION WITHIN TODAY, WOULD YOU ALSO ADVISE WHEN YOU EXPECT TO RECEIVE THE RESULTS.

THIS MESSAGE IS SENT UNDER RESERVATION OF ALL OUR RIGHTS.



"John Krzywkowski" <johnk@k-law.gr> 08/01/2008 19:33 To "Andrew Speake" <aspeake@blg.co.uk>

cc bec

Subject RE: NICHOLAS M - at St. Petersburg

History:

S. This message has been forwarded.

Dear Sirs.

I write in connection with your clients' message below to my clients.

As you should be well aware, your clients and Uniapro are beneficially owned/controlled by the same entities. The fact that Uniapro recently chartered the vessel and the faultless condition of the cargo on outturn under that recent charter at St. Petersburg should have led you to question the appropriateness of your clients' allegations that the vessel was in some way responsible for the cargo damage found on outturn at St. Petersburg. Vessels' conditions do not deteriorate so rapidly that your clients should insist on blaming the vessel when the evidence is so clear [all analyses show little (irrelevant) if any salt water in the damaged cargo] that the damage is of a pre-shipment nature. I note that you have failed to respond in any way to Owners' observations that the damage was pre-shipment.

Regarding the remarks which the Master was willing to add to the Statement of Facts, in my nearly thirty years as a shipping lawyer I have seen many such documents where the parties were properly prepared for both sides to include their remarks so that the document would reflect a comprehensive picture of the relevant events albeit not necessarily accepted by both parties. For some unknown reason, your clients were not prepared to follow this customary practice. In fact, it is my understanding that the Master has a clear right [and possibly an obligation] to record his objections to any aspect of the SOF. [I need hardly suggest as an example a tribunal questioning why a master failed to record his opposition to the contents of an SOF on its face.] My clients see this as yet another example of your clients' unnecessarily difficult behaviour and modus operandi — and my clients reserve their rights to claim damages against your clients.

As you have seen fit to support your clients' frankly indefensible attitude to the incorporation of the Master's comments on the SOF, for the record, I set out the comments that the Master was prepared to add to the SOF:

### QUOTE:

- 1. DESPITE THE FACT THAT COMMENCEMENT OF CARGO DISCHARGE FROM HOLDS NR 2 AND 4 WAS DELAYED FOR REASONS BEYOND VESSEL'S AND/OR OWNERS CONTROL AND RESPONSIBILITY. THE DISCHARGING PROGRESS AND THE OVERALL DISCHARGING TIME WERE NOT AFFECTED AS THE VESSEL WAS ALMAYS ABLE TO PROVIDE THE REQUIRED GANGS (ONLY 1 AND DURING SOME VERY LIMITED PERIODS 2 GANGS) FROM OTHER AVAILABLE HOLDS. THEREFORE NO DELAYS FROM VESSEL'S SIDE OCCURED DURING DISCHARGING OPERATIONS.
- 2. FROM COMMENCEMENT OF DISCHARGE UNTIL COMPLETION OF SAME, DISHARGING OPERATIONS WERE CARRIED OUT WITH 1(ONE) AND DURING SOME VERY FEW LIMITED PERIODS WITH 2(TWO) GANGS. ALSO THE AVAILABILITY OF WAGONS WAS ALWAYS VERY TIGHT.
- 3. ON 28TH DEC 2007, LAST MINUTE OLTRASOUND TEST WAS NOT CARRIED OUT FOR THE REASONS EXPLAINED TO CHARTERERS IN WRITING, WELL IN ADVANCE AND PRIOR BOARDING OF THEIR SURVEYOR (SGS). RELEVANT MSG IS AVAILABLE HERE AND DISCLOSABLE ON ANY COMPETENT AUTHORITY'S REQUEST.



- 4. CN 28TH CEC 2007. AFTER COMPLETION OF DISCHARGE, VESSEL WAS AWAITING PILOT DUE TO BAD WEATHER CONDITIONS (AS PER AGENT MSG, PILOT WAS NOT TO BE EXPECTED BEFORE 29TH NOON SUBJECT TO WEATHER IMPROVEMENT). RELEVANT MSG IS AVAILABLE HERE AND DISCLOSABLE ON ANY COMPETENT AUTHORITY'S REQUEST.
- 5. THE TOTAL QUANTITY OF CARGO DISCHARGED FROM HOLDS NR 2 AND 4 AS 'CAMAGED' OR 'SUSPECTED AS DAMAGED' WAS 214MTS (TWO HUNDRED AND FOURTEEN) AS PER CARGO UNDERWRITERS' AND ATTENDING PARTIES' CALULATIONS. AGENTS HAVE CONFIRMED SAME AND RELEVANT MSG IS AVAILABLE HERE AND DISCLOSABLE ON ANY COMPETENT AUTHORITY'S REQUEST.
- 6. TIME OF AUTHORITIES' PERMISSION TO COMMENCE DISCHARGE FROM HOLDS 2 AND 4 AS PER AGENTS' MESSAGES. RELEVANT MSGS ARE AVAILABLE HERE AND DISCLOSABLE ON ANY COMPETENT AUTHORITY'S REQUEST.
- 7. MASTER HAS SIGNED THIS SOF WITHOUT PREJUDICE AND WITH THE RESERVATION OF VESSEL'S AND/OR HER PAI CLUB AND/OR OWNERS' AND/OR THEIR MANAGERS' RIGHTS FOR ALL AND ANY, DIRECT OR INDIRECT, DAMAGE OR LOSS THEY MAY SUFFER FROM CHARTERERS' AND/OR RECEIVERS' AND/OR THEIR PRINCIPALS' AND/OR THEIR AGENTS, ACTS OR OMISSIONS.
- 8. ALL CARGO DISCHARGED AS PER 8/L AND CARGO MANIFEST.
- 9. AFTER COMPLETION DISCHARGING, HOLDS NOS. 1, 2, 3, 4, 5, 6, AND 7 INSPECTED AND FOUND NO CARGO REMAINING ONBOARD, ALL HOLDS WELL EMPTIED AND SWEPT.

Name and signature (Agents) AMADO C. APILATO ANTEKS/Alexander Konyukhov NICHOLAS M " UNCOOTE CAPT.

MASTER/M.V. "

For the record, it is denied that Owners or the crew were disruptive and unreasonable. My clients reserve their rights to claim damages in respect of your clients' actions at St. Petersburg.

Finally, my clients made you clearly aware of the circumstances in which Class was temporarily suspended pending repairs to mechanisms relating to No.6 hatchcover - which suddenly suffered problems during discharge operations. Nold No.6 appears to have no connection whatsoever with the locations in which demaged cargo was found, whatever the cause of that damage. Accordingly, your questionable reference to the temporary suspension of Class, or indeed to the more inflammatory suggestion that Class was entirely withdrawn, as having any connection with the factual matrix of the cargo damage for which we are both instructed, is very regrettable, unprofessional and lacking the integrity normally required of marine solicitors to reduce, rather than exascerbate, the difficulties faced by disputing parties in order to resolve them as cost-effectively as is reasonably possible.



Sest regards,

John Krzywkowski

Information in this =-mail (and any attachment) is confidential and may be legally

privileged. It is intended solely for the attention of the addressee(s). If you have

received it is error, please notify us by return e-mail and then immediately delete

this message from your system. Please do not copy it or use it for any purpose, or

disclose its contents to any other person; to do so could be a breach of



"Operations Congentra" <operations@congentra.co m>

28/12/2007 20:32

To "Eurof Lloyd-Lewis" <elfoyd-Lewis@blg.cp.uk>

cc

bcc

Subject FW: Ultra Sonic Inspection

----Original Message----

From: Master NicholasM [mailto:Master.NicholasM@telaurus.net]

Sent: Friday, December 28, 2007 10:48 PM

To: Operations Congentra Co: operations department

Subject: Ultra Somic Inspection

FM: MV NICHOLAS M TO: CONGENTRA AG REF: 236/28-DEC-07

i refer to your below message.

charterers have ignored my previous message and sent on board their surveyors (sgs) to carry out a survey which for the reasons already explained neither they have the right to perform nor there is a significant reason.

i do not understand charterers acts and way of thinking! what charterers mean "DETRIMENTAL CONSEQUANCES ARISEN THEREOF"??? why to place the vessel

\*OFF HIRE\*???

master's and owners position regarding said survey remains as stated in my last and we expect charterers to perform all their obligations under the c/p.

case of damage dargo is in charrs and owns lawyers hands and charterers must

stop threaten vessel and owners.

finally note that since completion of discharging earlier tonight vsl is waiting for improvement of weather conditions in order pilot who will shift the vessel to anchorage to be able to be dropped off safely, agents shall

revert once pilot becomes available and allowed to sail.

be guided accordingly.

brgrds,

master



"Operations Congentra" <operations@congentra.co m>

28/12/2007 21:29

To "Master NicholasM" < Master NicholasM@felaurus.net>

cc "Eurof Lloyd-Lewis" <elloyd-Lewis@blg.co.uk>

bec

Subject RE: Ultra Sonic Inspection

Dear Sirs,

You must have learned from the correspondence with our lawyers regarding your refusal to allow ultra sonic inspection that we reserve all our rights and hold you fully responsible for all consequences of such refusal.

As you know the vessel has to be redelivered as per  $\ensuremath{\text{c}}/\ensuremath{\text{p}}$  DLOSP St.Petersburg.

Therefore you should proceed for redelivery DLOSP St.Petersburg and act and give redelivery notice as per c/p. In the meantime we reserve all our rights.

Regards, Congentra AG

## PORT STATE CONTROL NOTICE OF DETENTION FOR THE MASTER

No.	
The undersigned: Harbour Master of the port of State 12 12 12 12 12 12 12 12 12 12 12 12 12	solifies you that
the ship: NICHOLAS M	call sign: 3882680
MO nyember: 7433452	gross tonnage:
port of registry: KIN6STEWA	foo state: St Vinchet & Bread in Es
type of ship: BULK CARRIER	date on which keet was laid: 1973.
OWNER CHIAN EPIRIT HARITIME ENTERFE	
agents: ANTEKS"	destification society:
berthed at: ISERTH AR. 43	
has been detained in accordance with the provision. Understanding on Port State Control and Article 80 Federation, on account of:	s of Section 3 of Paris Mamorandum of of the Membart Shipping Code of pe Russ an
We will one or more of the criteria for detection set and Convol.	in Sadios 9 of Paris Memorandum on Post \$1.252
crew members heing unable to provide proof of to them as specified in the Annex to the Interna- Certification and Watchkeeping for Soutarers,	if professional profesency for the duties assignied abonal Convention on Standards of Training. 1978/95, as amended:
mester or crow unable to comply with operation mentioned in Section 2 of Paris Memorandum	nel requirements as contained in the Conventions on Port State Control
<ul> <li>other deficiencies which, individually or togethe environment;</li> </ul>	er, are dearly hazardous to safely, health, or
☐ the fact that the Port State Central Officer was	abstracted in the execution of his duties,
For forther details see the Report of inspection, forth	ns A and B encosed to this Notice for the Magtor
On account of the above it is prosubited to shift the side Herbour Master, or to proceed to see without a p	hip to another besth without the prior consent of proper Notice of Release of ship from determion.
place: Port of St. Portur shalls	Dome: Decreption 29, 2004.
The above mentioned itarbour Master.	LONG - 15 Can be.

THEAR OF SE PHYRIBARIUM PSCARO CEDE, ALEXANDER G. KARPENKO

Name of state MCACOL	9.S. 19	840 nomber 7433 452
19 Relevana cerisficaço(s):		•
a) rithe	b) issuing authority	c) dates of issue and expire
i, Cargo Ship Safety Equipment	BV.	13-08-09-12-01-08
2. Cargo Ship Safety Construction	h (d) (re- in- in- in- in- in- in- in- in- in- in	
J. Pastenger Ship Selety 4. Cargo Ship Sulety Radio		13 08 07 12 61 08
5. Decoment of Compliance		6412 CZ 12:12:12
6. Safety Management Certificate	anning Korpelia anning	
7. Land Line 8. Freezoliga of Pollution by Oil	75.1/	13.10.95 34.63.10
9. Sufe Manning Document	1-1-175	12000
\$11, Ship Security		
11, Tonnage FZ, Class		and the state of t
7 C C C S S		
	d) inferrescent on last letter	nuclete of angost survey
	gam of sauce)	Surveying authority pan Country
<ol> <li>Cargo Ship Safety Equipment</li> <li>Cargo Ship Safety Construction</li> </ol>	man and the bound of the control of	
3. Passenger Ship Safety		14
4, Cargo Ship Safety Radio	,	Antonio III de la composició de la compo
5. Document of Compliance 6. Safety Management Certificate		181.4* 1.441
7. Lund Line		
A. Prevention of Pallutian by Oli		
9. Safe Manning Parament 10. Skip Security	**************************************	The state of the s
11. Temage		
12, Class		rables over the control of the contr
20. Ship retated happedion action to	dectar.	
December with Resp.	⊠(Class info	and Clines part informati
🗌 A 🏿 ಗೆಕಡಿರುವಾರುಲ್ಲಾ ಇವರಿಗೆ	ied 🖫 jospanica :	suspended (XX) worlding priority impression
Ship detailed  ■ Company  Ship detailed  Ship det	☐ Repair port	go re-derain LL Next pert to re-detain
	No Cotention F.1 Stop allows	ej to sejj ejter jo-dokonion
1.1 MARPOL investigati		_
21, Policiencies:	⊑×o	Myca (see et ached FORM B)
22, Supporting documentation.	` <b>⊠</b> %	[] Yes (see anext)
	SUM LEGISTER	PAUTICULARS
District aslice.		eraburg
Address:		pialitkaya Street, 198035 St. Poterskorg, Russia
Tylephour:		27 4194
Telefas:	(312)	27 4619
E-madi	อเจยรก	າກ.ຊຂຮະນີພະກະຊິງຄ
Name (duly aichorized FSCO of sepa		
	No.2	STYPOTON, M. SHELLUB
Signature:	Á	
	14	The hand
	1.57	
	7.0 25	6 / KSE 3900 a F / /
This report must be intrined on b	ward for a market where tower	two years lend affective charging available for consultation



### REPORT OF INSPECTION IN ACCORDANCE WITH THE PARIS MEMORANDUM OF UNDERSTANDING ON PORT STATE CONTROL \*)

Ребері Матіхіно Афрафізаціон Rozhdestvenka St., 1/4 (4990) 2 Minerow, Russian Federation +7 095 926 1000, 17 095 926 1311 meទាលខេត្តប៉ូ<u>ត្រីខ្</u>លាននេះការ

. copy to:

- master

- head office

- PSCO

ម៉ែតាំទីក្រ នៃ⊲៦ដល់±១២, យក្ខម្ម វ**ុ**;

- flag State

- recognised organisation, if applicable

SHIP PARTICIN AR	<u>s</u>		-
l. Nome of Skips - 🏄	CHOURS M	L. Flag of ship: \(\sum_{\textstyle \textstyle \textsty	LUCENT B GRENADIA
3. Type of ship:	BULKER	4. Ca8 sign: \$24	8B2680
5. IMO number:	7433452	6. Grass tomosge: 📿	1912
7. Date keel leis / major	совметкіля колькосного	1937	17 (A. Hannestone (commence)
8. Desilweight [where ap	plicable);	_,	ran-181-17 -1
	(les) responsible for issuance of el		
· · · ;- · · · · · · · · · · · · · · · ·			d - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
Di 47			
	(hos) respunsible for Issuance of m		
	n in the state of		
	កក្នុងសម្ភា (lde:rice) to គួនគឺជាតែវ ខន វ៉ា		
CHUAN ST	IRAT SAME 1571	IE ENVEDDRI	SESING
			EUS , GREECE
_	harterer: (Only ships carrying liqui		
□ Denisé Charter □ First Charteres	Maine Chartes Tinet Charter	_ Voyage Charter □ Not available	☐ Not applicable
CONGEN	TRA A. B. G. P. C.		
			y 11 11° 4] - M1 91. 4
12, កិច្ចភា៩ ជនជំនាំង្គមសម	of master to carrify (ha) the inform	unima under II.kş carenete 📝	. / 1
Name: AMAGO	C. APILAGO	Signature:	x 6. (
		({	(1
INSPECTION PARTI		·	
13. Date of first boarding	22 12 07	13b. Date of final report	bi _
14. Place of inspection:	St. Petersburg		
15. If vessel is detaileed :	date of issue of Detention untitle	1 F . Babbannon	
16. Type of inspection:	🗋 Initial inspection	Myore destribed inspection	Tapandes inspection
	🗆 Fullow-up inspection	Dienkow-op deseption	□(c.)r.c.
	Operational control		•
17. Operational controls	Abanden Skip	Note drift	Strily Water Sep. ##sted
(ifany):	Emery. Fire Pump	🖾 Бателение у Селегатог	Emergency Steering
	Communication eq.	Damage control	BOTHERY'S LB ENGINE
18. Arens inspected;	Mayigation Bridge	⊠Carga bold(s) / tubk(s)	Ballase tank(s)
	⊠,£ccommodating / Calley	Zisteuring-gear room / Engir	ae spain
	Zlderke: Folgisie	Prospenger spaces	Car stech

<sup>&</sup>quot;I't his inspection report has been fested solely for the corpose of informing the regular and other peet States that an inspection by the port fixer. escalation in the herding, has differentiate.

Continuous in the meaning, was observable.

This inspection report common the commend as a scancombiness equilibrate in excess of the equilibrate the ship is required to easily.

This inspection report commends to supply and eight codes 17. For correct full posterology of company.

\*\*\*\*(Masters, Shipperstars and in Operators are advised that detailed to the nation on the inspection may be subject to publication. Quantitation of the

\*\* \*\* \*\*\*\*\*\*\*

· andit decit.

Rubideeverks St., 141 (15012 Masons, Russen Federation, +7 C95 N25 1903, +7 G55 U26 (15) (Introversity)

Federal Etaritizat Artministrazan

cepy for a magner - item office - psgo

steken is december, angy te - Gog State - recognised ingromentary it gup labels 1. Same of ships All Contract ( A S.

oleno central	Tafferday military	PARTICIPACION DE LA COMPACION	MALICHENCIES EQUIDA AND TOLLOW VE ACTIONS CON	SOLL PERSONS	
301114			Cantellillop (etc. ')	Action takes 3	Additional community
いればれ	Catherra Start	LETTE DE BULL		4	RY BY AS DED NOTIENCATIONE
	CHEET'Y CONSTRUCT	,1			ンとはたり、これについる
	The state of the s		4417.44.44.44		The state of the s
	7.1.CM				į
361.0	とはなけられていましまり	では、一般を入りしている。			
to Button.				1	Control Same Sand of the Section Secti
411					WENCHALL RY RV.
		:			
		F			CANAL CHANGE TO THE SECOND STATE STA
	***************************************	Annual Communication of the contraction of the cont			047 ED 62 CA CA
がない。	SECREPATIVE	SACADAIN. ADD. AC		12	And the second of the work
				471.00	イストライン・アントライン・アントライン・アントラン・アン
*******	がなった。これにおいて、これは各人は他の	だS			
35.60	6.4-10.6.W. A.S.	GANGUAS ONCACE		ή	
		The second of th	14		Land Land College Control Cont
20 20 20 20 20 20 20 20 20 20 20 20 20	MASKILLE	MANNING MISSIALG		1	2 ND OFFICER ANSSYSE I
	なのでは、これので				
The second secon	人もともメルラボレギ	ACCOUNT TO SELECTION OF THE CONTRACT OF THE CO	***************************************		
	MINIMUM SAGE	1			
	10 4 6 11 11 11 11 11 11 11 11 11 11 11 11 1				
THE CONTRACT OF THE CONTRACT O	CALLEGE CONTRACTOR CON			Proceed than pro-	
0660	CIRE JACKETS NOT AS	A27 A-5		4	アングラグ アンメアン プログラ アンダング
		がおなどの内			
Name (	dus anisosos io CSSS basistana vide	VOYAGUS / STUPANOV	M. SHE	103/15	
	Company of the second state of the second stat		The second secon	er sagen inchestication (signature)	The state of the s

11) Medis, Shipwardis and it Openhas we should that denied infamore on the inspection may be subject to implication (wow, gains may or earlied in the best hand on the commendation in its exammendations a full to very security. requedate is made. 5. In he completed in the event of a decexion (RF resides members ships <500 G). For returness amby). 8.500 retents side of from B for Estit bases.

. . . . . . .

....

And soft desirations are rectified distins on applications for re-

.... JIDIL URSIL.

REPORT OF INSPECTION IN ACCORDANCE WITH THE PARIS MEMORANDEM OF UNDERSTANDING ON PORT STATE CONTROL

Rozhkastenka St., 1.) Judyol I. Meytsia, Rassam Petkenian –7 085 926 (1001, +7 10)5 926 (5) ( Filializand@princip Federal Vanitima Johnanismien

if ship is detained, copy to . . Jay Stae · teoppisable

obry to: v master v food offer 938

1. Hums of ship: A. C. C. K. C. A. A. S.

.... Signeruze Name (duty authorized 1860 of reporting notherity) Mile S.W. PHKO. K. ...... Mile SKEELSHEEL GREEN.

\*\*\*) Manner, Stypomery unifor Openius are alwined that helping extendence of the country to analyze to publication (amount).

This inspection was not a full invey and deficiences lead may not be extallistics. In the event of a defoultie, it is commissed along full survey is consolited in the event of a defoultie, it is commissed along full survey is consolited in the event of a defoultied full interest in the event of a definition (in the event of a defoultied full interest in the event of a definition (in the

:

# REPORT OF INSPECTION IN ACCORDANCE WITH THE PARIS MEMORANDOM OF UNDERSTANDING ON PORT STATE CONTROL

4. Place of inspection St. Petersburg 2. Mel Duranderr RG334, S.C. J. Date of Boat reports if ship is detained, expy in: « flag buts. • recogniced organism in applicate apprile, i maska i head office . 2009 1. Mande of strip: MCACOLASS. M. Followy Marshaw Administration Reduction Reductions 54, Fit 1990 Mesons, Austin Federales, C 2007 926 1960, 77, 005 926 1961 mensand@pma.no

<u> </u>	Chan respi)	MURRELE MISSIMIA, FIRE	SOKES DIMMERED AND HELLED TO SOLVE SOLVED TO SOLVE SOLVED TO SOLVE	MISSIM GOVERNMENT COLUMNIA COL	SOUTH THE ENDS TORE AND LI	BULLINE BY TRON 19410	DECK TO STOPE ROCK	Photos Land Come Come De De Come	Martin At State Land College C	CMA CAPACITY 3280UEM	CE CE	LAST NM CALRESTED (32,11.02)	Supportance annual property of the support of the s
PRESCRINGUES FOUNDAMENTALINA MILACTIONS	ickery) Converton ref. 7 Artistic lahen 4	CULPED,	the state of the s		A	D SWRYKURY 30		the state of the s	314 HARCHES & C. 150	Principal Commence of the Comm		D. T.R.	Numer 14-11/2 authorited 7800 of reparting watherings M. S.T.L. DAREGOL M. S.L. S.L. S. C. C. Sterndare Sterndare
	EIRE FIGHERAL AS	A DOS LAST OF THE STANDARD BY THE STANDARD OF	MCDELLE OTTER		A CONTRACT OF THE PROPERTY OF	BUILTHERD - KAGKED	CORROSIEM	KUKKKED: 70 FF		Hilliand and the property of the control of the con	The second control of the second seco	PUBLICATION NOT US TRO	aly aethotized 2800 of reputting withoutest $\#_{n, \Sigma} \Sigma \Sigma_{n, \Sigma}$
:	0.930 0.930 0.930		6851	0.087	143,071.1.	0.925	:	0985			* C. L.	22.5	Nuori

an application for re-\*\* Marker, Shipers are supported an estying that desired infantation on the Inspection may be subject to publicately favor partennions). This imprecion was not all strong and definition land may not be considered in the extent of a definition, it is recombined to the in the survey is copied out. flymedick grinske. O'Tsi be completed in one event of a Colorfical (fiv. light-occuention, chips 1-306 OT for reference recks). It is noted you as firm is fan fall bibels.

- as any weekshapping on

# REPORT OF INSPECTION IN ACCORDANCE WITH THE PARIS MEMORANDUM OF UNDERSTANDING ON PORT STATE CONTROL

100p) 10) - masket - bead olities

ŝ

199012 Musemu Rassier Fideralieu 17 ang 926 1000, -2 d95 926 1981 Potenti Marionia Adalamatastera Resolution version of a 18. та канаўўритомамі

1 Name of Ship: N. Cotto C. R.S.

 racognised organization, if applicable if strip as skeningtly pupy say . Bug State

DEFICIENCES POUND AND EQUADISTIC ACTIONS TO

2. DAO DEMONDE PARTINES 3. Date of Suid report .............. 4. Place of Ingresons. St. Petersburg.

\*\*\*) Microst. Siliproviers and a Systations are advised that detected in the inspection may be scalar to employeed, we require that a Systation was not a full year by and definition or a second and an including which are supported in the country of the second and all definitions are a full year by an including an analysis of the second and all definitions are

Name (dely sufficient PSCO of reporting pathents) K., S.T.W.R.K.C.K...., M., S.K.E., S.K.E., Signature .....

grepteden is mean. If in the completed in the event of a generation (for part-convention shops ship) GT (an effective unit). The previous interest form if in the lights.

. . . . . . . . . . . . . . . .

REPORT OF INSPECTION IN ACCORDANCE WITH THE PARIS MEMORANDUM OF UNDERSTANDING ON PORT STATE CONTROL ...... 4. Peters of Ingression: St. Petersburg al skip is delained, anny a — ing dang - rangarska ny paolisanana i Sypolicable 2. IARD marchet: 2323.345.2 3. Date of Shall reports. ospy w i kinadaffar Haddaffar HSCO 109512 Moures, Russian Essentian +7 695 425 1000, +7 195 925 1133 Federal Maritman Administration Recolabolismika St., 19 <u> முறைத்தொலை</u>

	SPD COLORER CALIFORNIA CONTRACTOR	LAUGHTE TYPE OF	MAKERSIEN SUKE	NO EXIDENCE ST. ME/ME	ASC. CXIERAM TEST -	NORTHER CONDUCTOR	GMX,Y 8是7在57年D		ZAD OFFICER ABSENCE	FOR MORE THAN IT DAYS	(このなど、こんなろのは、)	P/S WAVIGATION LIGKT		LIBRET UNGIT	CONTRACTOR (30 AND OF TEST	Signature Signature
DEFICIENCIES FOURD AND FOLLOW REACTIONS (**)	Aviton takes 1)			- A.								47			77.	CHRECK
TONE GENERAL SAL	Cunwation ref. by		***													
KADIEN	Nature of defeative	-	10 to 47 [6/24	MALLE KADIC DOT LS	があるこのでし		distribution and a company of the company	CONSTANT LAST INGOMPLETE.			marana a de la constitución de l	CLALKES SKAPES LNOPARATIVE		Handa and the second se	OF FINALITY OF	ONY ALSTUPPACOL
	Defective in the Control of the Cont	7TN	ALS VIR CICKLOS	MALKE KADIO	LASTA CLATON AND WILLIAM		Charles of the control of the contro	7222 TAKE 745 X		111		CARKES SERIE	SCHOOL SCHOOLS	A Commence of the second secon	GMDSS EBUIPMENT FRANKLINGTO	Name (daly southerized 1950) of reporting nationary Als STUPARED Commenced States of States of States and States of
	Group code		1000	2.00 A. 3	-	:	0,70	#:::::::::::::::::::::::::::::::::::::			( )	25.55		77870	7	Name (d)

\*\*\* ) Makkas, Shipuwaca and an Operand the Applied information on the Impection may be subtant to publication (www.parismon.org). This independent was not a full survey and deligation of the generalized may contract the generalized may contract the generalized of a detailmining it is uncommended that the series is narrounded that the series is narrounded that the series of a detailmining it is necessarily that the series of the seri

ingreditin ke*mzae* ) Eschakteapland in its esemi of a describbniffer non-ansversion skips 5500 GF for reference only). ) See rekesso adeaf form B for fall takes.

REGION DIO ARTICAT

(Form B)
Codes
Takon
Action
Definiency

deficiently reclified	Secrety deficiency, of peak point	reathy deficiency within 14 days	recify defisionsy before departure	recify non conformity within 3 months	techily major non-conformity before departure	Competent Security Authority Informed	detainable desicienay	as in the agreed class covalities	faq shale consuled	patient attention	classification society (responsibility in caso of delainable deficiency)	teme, substitution of equipment	temp, repair to be carried out	letter of warning lagred	letter of warming syllidaws
	•						. 08		8	92	70 (lickbox)**			96	

# PSC Inspection Action Taken Codes (Form A)

ali daliziencies ractilos	ship banned	ship expelled on security grounds	ship delained	ship allowed to sail efter detertion	ship allowed to sall after ro-detanion	next part infermed	ecity detainable deficiencies at next port (next part to reversi	(eethy detainable deficiencies at agreed (epsir port froza) port	Day stale/consul informed	Inspection suspended	classification socialy informed	ewestigntion of contraversion of discharge apovision (MARPOL)
12 (fickbox)	20 (fickbox)	27 (fickbox)	30 (lickbox)	35 (ilekbox)	36 (fickbox)	(O (tickbox)	45 (fickbox)	46 (fighthor)	50 (aickbox)	60 (tickbox)	70-(Gckbox)**	85 (lickbox)

- DESPITE THE FACT THAT COMMENCEMENT OF CARGO DISCHARGE FROM HOLDS NR 2 AND 4 WAS DELAYED FOR REASONS BEYOND VESSEL'S AND/OR OWNERS CONTROL AND RESPONSIBILITY, THE DISCHARGING PROGRESS AND THE OVERALL DISCHARGING TIME WERE NOT AFFECTED AS THE VESSEL WAS ALWAYS ABLE TO PROVIDE THE REQUIRED GANGS (ONLY 1 AND SOME VERY LIMITED TIMES 2 GANGS) FROM OTHER AVAILABLE HOLDS. THEREFORE NO DELAYS FROM VESSEL'S SIDE WERE OCCURED DURING DISCHARGING OPERATIONS.
- FROM COMMENCEMENT OF DISCHARGE UNTILL COMPLETION OF SAME, DISHARGING OPERATIONS WERE CARRIED OUT WITH HONE) AND SOME VERY FEW LIMITED TIMES WITH 2(TWO)
  GANGS, ALSO ALWAYS AVAILABILITY OF WAGONS WAS VERY TIGHT
- ON 28TH DEC LAST MENUTE ULTRASONIC TEST WAS NOT CARRIET OUT FOR THE REASONS EXPLAINED TO CHARTERERS IN WRITTING, WELL IN ADVANCE AND PRIOR BOARDING OF THEIR SURVEYOR (SGS). RELEVANT MSG IS AVAILABLE HERE/DISCLOSABLE ON ANY COMPETENT AUTHORITY'S REQUEST.
- ON 28TH DEC AFTER COMPLETION OF DISCHARGE VESSEL WAS WAITING PILOTAGE DUE TO BAD WEATHER CONDITIONS (AS PER AGENT MSG PILOT WAS NOT TO BE EXPECTED BEFORE 29TH NOON SUB WEATHER IMPROVEMENT), RELEVANT MSG IS AVAILABLE HERE/DISCLOSABLE ON ANY COMPETENT AUTHORITY'S REQUEST.
- THE TOTAL QUANTITY OF CARGO DISCHARGED FROM HOLDS NR 2 AND 4 AS DAMAGED! OR 'SUSPECTED AS DAMAGED! WAS 214MTS (TWO HUNDRED AND FOURTEEN) IN TOTAL AS PER CARGO UNDERWRITTERS' AND ATTENDING PARTIES CALULATIONS. AGENTS HAVE CONFIRMED SAME AND RELEVANT MSG IS AVAILABLE HERE/DISCLOSABLE ON ANY COMPETENT AUTHORITY'S REQUEST.

[2/29/2007

Page 2 of 2

- TIME OF AUTHORITIES PERMISSION TO COMMENCE DISCHARGE FROM HOLDS 2 AND 4 AS PER AGENTS MESSAGES, RELEVANT MSGS ARE AVAILABLE HERE/DISCLOSABLE ON ANY COMPETENT AUTHORITY'S REQUEST.
- MASTER HAS SIGNED THIS SOF WITHOUT PREJUDICE AND WITH THE RESERVATION OF VESSEL'S AND/OR HER P&I CLUB AND/OR OWNERS' AND/OR THEIR MANAGERS' RIGHTS FOR ALL AND ANY, DIRECT OR INDIRECT, DAMAGE OR LOSS THEY MAY SUFFER FROM CHARTERERS' AND/OR RECEIVERS' AND/OR THEIR PRINCIPALS' AND/OR THEIR AGENTS, ACTS OR OMISSIONS.

Page 6 of 16

+++++++++

From Owners broker:

FRM: LIGHTSHIP CHARTERING A/S, GENTOFTE Zhivko-Slawek-Dimitris/Soeren

good afternoon

nicholas m/BBL

with ref to yr last msg, flw from the owners

From: C.S.M.E/ Chartering Dept.

To: Billmar Chartering

Re: MV "Nicholas M." Acc "ERITANNIA BULKERS A/S," cpdd 18th Dec 07 / Update on vsl's loading readiness.

pls urgently relay foll msg to charrs.

TOP URGENT

dear sirs,

we refer to our recent exchanges regarding the subject matter; while you will find in the following lines our reply to your last we would like once more kindly request charrs to carefully read both the contents and the attachment of our last msg which will definitely assist them to comprehend the current situation.

charrs urgency to load the vsl has been duly noted along with the reservation of their rights"...for any and all possible consequences arising from this situation".

while the former is fully understood and respected, the latter is not acceptable since it is obvious that the charrs will accept the vel for loading when she will become ready for the same; otherwise owners fail to comprehend charrs decision and relevant recent instructions vessel to be supplied with the necessary for the scheduled voyage 200mts of low sulphur ifo yesterday and today (delivery now in progress) with the remaining 700mts regular ifo and 150mts mdo, being them and their agents already aware about the developments of last saturday's noon and the current status of the vessel (see also our below mag sent to charrs, for sake of good order, both directly by the master as well as through the broking channel).

please be sure that owns do not just rely on charrs understanding and cooperation practically shown by their decision not to exercise the right to cancel the vsl and from the very begining have done their best in order the vsl to become ready for loading the soonest

Page 7 of 16

possible. however due to the prevailing holidays little progress in that direction has been noted as we have faced most parties involved absolute unwillingness, irrespectively of cost, to work during the weekend and before new year's holidays.

more specifically the vessel was detained for the following three deficiencies; firstly, during final closing operation of cargo hold nr 6 aft panel due to mishandling the relevant hydraulic cylinder jack was damaged preventing the opening/closing of said part of hatch cover and though same was finally closed and until completion of repair of same prior loading or even prior sailing the vsl could load with only fore part of hatch cover to be in open position - attending class surveyor seems to share our opinion - local PSC authorities considered same as ground for detention(PSC group code: 1240...PSC comments:

metal hinges torn out from base hold or 6 due to damage of hydraulic system).secondly, during PSC inspection it was discovered a small hole in the lowerpart of accommodation superstructure.(PSC group code: 0985...PSC comments:

bulkhead from main deck to stere room holed).Lastly, it was also found a temporarily repaired slight leakage of bilge tank (PSC group code: 0985....PSC comments: leakage from bilge collecting tank into e/r).

while for the above last one minor deficiency no workshop is required for its repair (already in progress by the vessel's fitter) for the other two we have investigated all possibilities and unfortunately the repair from class approved workshop and special permissions from port authorities (bureaucracy procedures) are needed and the problem is ,as it was said, that has now become obvious that due to the holidays nobody (irrespectively of cost) wants to work; especially for the repair of the damaged hydraulic cylinder and its foundation, as far as we understand from our technical department, same should be dismantled by shore team and to be taken ashore where its pin will be modified to the fortunately existing on board spare one.

in order to further reply your questions as imposed in your last, please also be advised that vessel's class and flag have been informed by the owns about the vsl's detention and while the class surveyor has already attended the vessel (he was also onboard before the incident giving instructions for the repair of nr 6 aft panel) and stands by for the supervision of the necessary repairs, all other parties simply do not care and they only request us to be patient.

another problem the owns have is that they cannot sent on board their superintends to speed up matters as the consulate is closed due to holidays and no visa can be provided to them; this is also relevant to the serious problem the owns have encountered and they still face with their previous charrs and their agents for the reasons already briefly explained in their last message to

Page 8 of 16

you (pls read carefully same again). for this reason owners from the very begining made known to you and your agents their intention to appoint messrs "rusnautic shipping" to act as owners' protecting agents, in which case you will also be in position to constantly have from first hand updates about the vsl's readiness, however their reply was that they first expect your authorization in order to accept same which please urgently provide in order owners to have the assistance of agents who will not only care about the ship but also protect her and her new charrs interests. in such case it is well understood that all related there to costs will be for owners account and for this reason furthermore, in order to provide charrs with a realistic although under the circumstances preliminary guidance about the vsl's expected loading readiness it can be said that actually maximum two working days after new year's holidays are to be needed for the rectification of the above items which prevent vsl from her loading; however same estimation is given on an all going well and unforeseen circumstances always excepted basis as nobody can rely on the promises of the local parties involved; otherwise, please be sure that the val's master and owners are doing their outmost to have the val ready for loading the soonest possible which given the above can be expected on fri 4th jan agw uce wog.

in addition, please also be informed that the master is now in progress of preparing further vsl's holds in line with the recommendations of the relevant surveyor as well as that now obviously there is no any more the necessity vsl to go to the anchorage and then to proceed for loading; same can now be arranged to be done directly from the present berth to the designated loading bert.

honestly speaking, from the very beginning all information available here was made also available to the vsl's new charrs as the owns have adopted a straight forward attitude towards the next charrs who are in rush to load the vessel; this is the only proper, responsible and hopefully fruitful way of dealing with situations like the above and the people who do business with them.

lastly, we remind you once more the ultimate necessity of charms prompt confirmation directly to messrs "rusnautic shipping" with regard to their consent for the appointment of them from owners' side as vsl's protecting agents too.

we thank again charrs nice cooperation so far.

as always we remain,

kind regards,

chartering dept.
c.s.m.e(as agents only)

**++++++++** 

### Master NicholasM

From:

"Master NicholasM" < Master NicholasM@telaurus.net>

To: Sent: "operations department" <operations@chianspirit.gs> Monday, January 07, 2008 5:15 PM

Sent: Subject:

PSC DEFICIENCIES PROGRESS REPORT

FM: MV NICHOLAS M TO: C.S.M.E./OPER DEPT. REF: 029/07-JAN-08

DEAR SIR.

PLEASE FIND FOLLOWING DEFICIENCIES RECTIFIED

GROUP CODE DEFECT

ACTION TAKEN

0199 CLASS CERTIFICATE

RCVD 06-JAN-08

HULL ANNEX TO CLASS

STILL WITH BV, TO CORRECT

1420 CLEANLINESS OF E/R 1399 MOORING FREE T CONTINOUS IN PROGRESS

FREE THREE FROZEN (3) PEAR LEADS FWD 07-JAN-08

1240 IN PROGRESS BY SHORE REPAIR, EXPECT TO COMPLETE

08/01/08 PM 0543 EXHAUST PIPE IN E/R HOLED

HOLE COVERED TODAY

UPPER

PART NEED TO

BE

COVERED, ABT I DAY

JOB AS

PER C/E ESTIMATE

0956 GANGWAY UNSAFE

INSTALL ADDITIONAL

RAILINGS AT LOWER PLATFORM AS PER BV SURVEYOR ADVISE

REMARKS: FYG EXPERIENCED FRESH WATER PIPE BURSTING
THIS AFTERNOON IN THREE DIFFERENT LOCATIONS.
TWO (2) AT STBD BATHROOM MAIN DECK CEILING
AND ONE (1) AT ELECTRICIAN'S BATHROOM.

RE-SWEEPING OF TANK TOP IN CARGO HOLDS IN PROGRESS.

BEST REGARDS, MASTER

1/11/2008



Visa Page No 3 Página de visados nº. to the Holl Annex\* del Anexo Casco

No LPRO/GSA/20050519180535

NAME OF SHIP/Nombre del Ruque : NICHOLAS M Register No /Nº de Registro : 910W76

Visa*lVisado* No\*\*; 9.

Occasional survey of hull afloat Rec, 6.1, 6.2, 6.347.2 were dealt with Rec.7.1 partially done; cancelled for postponement.

Rec. 9.1: Oil leakage on hatch covers hydraulic cylinders to be repaired and tested. Meanwhile the leaked oil should he cleaned to prevent pollution Limit Date: 28 December 2007

AUEn : Maceio, Brazil Cn/El: 28 September 2007

Stamp/Sello

VisalVisado No\*\*: 10

(CONTINUATION OF VISA 5) Rec. 10.1: Cargo Hold Mr.1 forward batch cover girders found wasted to be cropped and renewed. Limit Date: 06 April 2008

AWEn : Maceio, Brazil On/El: 28 September 2007

Stamp/Seile

Visa/Visado No\*\*: 11

Occaional survey of holl afloat further to detention by PSC. Rec. 9.1 presently postponed. Rec.11.1: Oil leakage on hatch covers hydraulic cylinders to be repaired and tested Meanwhile the leaked oil should be cleaned to prevent polition. Limit Date: 28 March 20087

AVEn : St. Fetersburg . On/El: 11 January 2008 Stamp/Selfo

VisalVisado No\*\* : 11

(CONTINUATION)

Rec.11.2:

Repair as per attached list of recommendationsNr.LNGO/2007/J0100/hull to be performed at .coming dry-dock / intermediate survey. Limit date:

31 March 2008

AtEn : St.Petershurg Owler: 11 January 2008

Stamp/Szillo

Visa/Visado No\*\*:

ÁUÐa : Ou/EI:

Stamp/Sello

At : St.Percesbine Espedido en

10 January 2008 On:

By Order of the Secretar Por Orden del Secretario **RZAVYAŁOV** 



NESI 412a - Page 1/1

MY NICHOLAS 19.
910W76
St. PETERSBURG
28/12/2007

# NOTTELCATION

Due no THE PROBLEM WITH ECOSING OF AFT

HATCH COVER OF CAREO HOLD N. 6 AND

IMPOSSIBLLITY TO BETHER PRIOR STYPS

DEPARTURE CERTIFICATE OF CLASSIFICATION

NO. LPRO/LTS/2005-1074415530 HAS BEEN

TEMPORARILY WITHDRANN AS NEW AS

CARGO BUSP SAFETY CONSTRUCTION

CERTIFICATE No. LPRO/LTS/2005-1013783942



EVERNY ZAVYALON SURVEYOR TO BURETO VERITAS



# SOLAS

では、100mmの

Consolidated Edition, 2004

Consolidated text of the International Convention for the Safety of Life at Sea, 1974, and its Protocol of 1988: articles, annexes and certificates

Incorporating all amendments in effect from 1 July 2004



Part A: Application, definitions, etc. Regulation 2

# Part A Application, definitions, etc.

# Regulation 1

Application

- (a) Unless expressly provided otherwise, the present regulations apply only to ships engaged on international voyages.
- (h) The classes of ships to which each chapter applies are more precisely defined, and the extent of the application is shown, in each chapter.

# Regulation 2

Definitions

THE REPORT OF THE PERSON OF TH

For the purpose of the present regulations, unless expressly provided otherwise:

- (a) Regulations means the regulations contained in the annex to the present Convention.
- (b) Administration means the Government of the State whose flag the ship is entitled to fly.
- (c) Approved means approved by the Administration.
- (d) International voyage means a voyage from a country to which the present Convention applies to a port outside such country, or conversely.
- [8] A passenger is every person other than:
  - (i) the master and the members of the crew or other persons employed or engaged in any capacity on board a ship on the business of that ship; and
  - (ii) a child under one year of age.
- (f) A passenger ship is a ship which carries more than twelve passengers.
- (g) A cargo ship is any ship which is not a passenger ship,

### Chapter I: General provisions Regulation 3

- (b) A tanker is a cargo ship constructed or adapted for the carriage in bulk of liquid cargoes of an inflammable nature.
- (i) A fishing vessel is a vessel used for catching fish, whales, seals, walrus or other living resources of the sea.
- (i) A nuclear ship is a ship provided with a nuclear power plant.
- (k) New ship means a ship the keel of which is laid or which is at a similar stage of construction on or after 25 May 1980.
  - (f) Existing ship means a ship which is not a new ship.
  - (m) A mile is 1,852 m or 6,080 ft.
- Anniversary date means the day and the month of each year which will correspond to the date of expiry of the relevant certificate.

# Regulation 3

### Exceptions

- (a) The present regulations, unless expressly provided otherwise, do not apply to:
  - (i) Ships of war and troopships.
  - (ii) Cargo ships of less than 500 gross tonnage.
  - (iii) Ships not propelled by mechanical means.
  - (w) Wooden ships of primitive build.
  - (v) Pleasure yachts not engaged in trade.
  - (vi) Fishing vessels.
- (b) Except as expressly provided in chapter V, nothing herein shall apply to ships solely navigating the Great Lakes of North America and the River St Lawrence as far east as a straight line drawn from Cap des Rosiers to West Point, Anticosti Island and, on the north side of Anticosti Island, the 63rd meridian.

<sup>&</sup>quot;'Inflormable" has the same meaning as "floremable".

# Regulation 4 Exemptions

- (a) A ship which is not normally engaged on international voyages but which, in exceptional circumstances, is required to undertake a single international voyage may be exempted by the Administration from any of the requirements of the present regulations provided that it complies with safety requirements which are adequate in the opinion of the Administration for the voyage which is to be undertaken by the ship.
- (b) The Administration may exempt any ship which embodies features of a novel kind from any of the provisions of chapters II-1, II-2, III and IV of these regulations the application of which might seriously impede research into the development of such features and their incorporation in ships engaged on international voyages. Any such ship shall, however, comply with safety requirements which, in the opinion of that Administration, are adequate for the service for which it is intended and are such as to ensure the overall safety of the ship and which are acceptable to the Governments of the States to be visited by the ship. The Administration which allows any such exemption shall communicate to the Organization particulars of same and the reasons therefor which the Organization shall circulate to the Contracting Governments for their information.

# Regulation 5 Equivalents

- (a) Where the present regulations require that a particular fitting, material, appliance or apparatus, or type thereof, shall be fitted or carried in a ship, or that any particular provision shall be made, the Administration may allow any other fitting, material, appliance or apparatus, or type thereof, to be fitted or carried, or any other provision to be made in that ship, if it is satisfied by trial thereof or otherwise that such fitting, material, appliance or apparatus, or type thereof, or provision, is at least as effective as that required by the present regulations.
- (b) Any Administration which so allows, in substitution, a fitting, material, appliance or apparatus, or type thereof, or provision, shall communicate to the Organization particulars thereof together with a report on any trials made and the Organization shall circulate such particulars to other Contracting Governments for the information of their officers.

Control of the Contro

Refer to SLS.14/Circ.115, in intended, on the issue of exemption certificates under the 1974 SOLAS Convention and amendments thereto.

Chapter I: General provisions Regulation 6

# Part B

# Surveys and certificates\*

# Regulation 6

Inspection and survey

- (a) The inspection and survey of ships, so far as regards the enforcement of the provisions of the present regulations and the granting of exemptions therefrom, shall be carried out by officers of the Administration. The Administration may, however, entrust the inspections and surveys either to surveyors nominated for the purpose or to organizations recognized by it.
- (b) An Administration nominating surveyors or recognizing organizations to conduct inspections and surveys as set forth in paragraph (a) shall as a minimum empower any nominated surveyor or recognized organization to:
  - (i) require repairs to a ship;
  - (ii) carry out inspections and surveys if requested by the appropriate authorities of a port State.

The Administration shall notify the Organization of the specific responsibilities and conditions of the authority delegated to nominated surveyors or recognized organizations.

(t) When a nominated surveyor or recognized organization determines that the condition of the ship or its equipment does not correspond substantially with the particulars of the certificate or is such that the ship is not fit to proceed to sea without danger to the ship, or persons on board, such surveyor or organization shall immediately ensure that corrective action is taken and shall in due course notify the Administration. If such corrective action is not taken the relevant certificate should be withdrawn and the Administration shall be notified immediately, and, if the ship is in the port of another Party, the appropriate authorities of the port State shall also be notified immediately. When an officer of the Administration, a nominated surveyor or a recognized organization has notified the appropriate authorities of the port State, the Government of the port State concerned shall give such officer, surveyor or organization any necessary assistance to carry out their obligations under this regulation. When

<sup>&</sup>quot;Refer to "Global and uniform implementation of the harmonized system of survey and certification (HSSC)" and to the "Revised survey guidelines under the harmonized system of survey and certification" adopted by the Organization by resolutions A.383(21) and A.948(23) respectively.



applicable, the Government of the port State concerned shall ensure that the ship shall not sail until it can proceed to sea, or leave port for the purpose of proceeding to the appropriate repair yard, without danger to the ship or persons on board.

(d) In every case, the Administration shall fully guarantee the completeness and efficiency of the inspection and survey, and shall undertake to ensure the necessary arrangements to satisfy this obligation.

## Regulation 7

Surveys of passenger ships\*

- (a) A passenger ship shall be subject to the surveys specified below:
  - an initial survey before the ship is put in service;
  - (ii) a renewal survey once every 12 months, except where regulation 14(b), (e), (f) and (g) is applicable;
  - (iii) additional surveys, as occasion arises.
- (b) The surveys referred to above shall be carried out as follows:
  - the initial survey shall include a complete inspection of the ship's structure, machinery and equipment, including the outside of the ship's bottom and the inside and outside of the boilers. This survey shall be such as to ensure that the arrangements, materials and scantlings of the structure, boilers and other pressure vessels and their appurtenances, main and auxiliary machinery. electrical installation, radio installations including those used in life-saving appliances, fire protection, fire safety systems and appliances, life-saving appliances and arrangements, shipborne navigational equipment, nautical publications, means of embarkation for pilots and other equipment fully comply with the requirements of the present regulations, and of the laws, decrees, orders and regulations promulgated as a result thereof by the Administration for ships of the service for which it is intended. The survey shall also be such as to ensure that the workmanship of all parts of the ship and its equipment is in all respects satisfactory, and that the ship is provided with the lights, shapes, means of making sound signals and distress signals as required by the provisions of the present regulations and the International Regulations for Preventing Collisions at Sea in force:
  - (ii) the renewal survey shall include an inspection of the structure, boilers and other pressure vessels, machinery and equipment, including the outside of the ship's bottom. The survey shall be

<sup>\*</sup> Refer to resolution A,794(19) on surveys and inspections of ro-ro passenger thips and MSC/Circ. 956, Guidelines for unscheduled inspections of ro-ro passenger ships by flag States.

- .5 the Protocol of 1988 relating to the International Convention for the Safety of Life at Sea, 1974 (SOLAS PROT 88);
- .6 the International Convention for the Prevention of Pollution from Ships, 1973, as modified by the Protocols of 1978 and 1997 relating thereto (MARPOL 73/78);
- the International Convention on Standards of Training, Certification and Watchkeeping for Seafarers, 1978 (STCW 78);
- .8 the Convention on the International Regulations for Preventing Collisions at Sea, 1972 (COLREG 72);
- .9 the International Convention on Tonnage Measurement of Ships, 1969 (TONNAGE 69);
- .10 the Merchant Shipping (Minimum Standards) Convention, 1976 (ILO Convention No. 147) (ILO 147);
- .11 the Protocol of 1996 to the Merchant Shipping (Minimum Standards)
  Convention, 1976 (ILO Convention No. 147) (ILO147 PROT 96);
- the International Convention on Civil Liability for Oil Pollution Damage, 1992.
- 2.2 With respect to ILO 147 and the ILO Protocol 1996, each Authority will apply the procedures referred to in section 7 of Annex 1 for the application of ILO publication "Inspection of Labour Conditions on board Ship; Guide-lines for procedure".
- 2.3 Each Authority will apply those relevant instruments which are in force and to which its State is a Party. In the case of amendments to a relevant instrument each Authority will apply those amendments which are in force and which its State has accepted. An instrument so amended will then be deemed to be the 'relevant instrument' for that Authority.
- 2.4 In applying a relevant instrument, the Authorities will ensure that no more favourable treatment is given to ships of non-Parties or to ships below convention size. The Authorities will thereby apply the procedures specified in section 3 of Annex 1.

#### Section 3 Inspection Procedures, Rectification and Detention

- In fulfilling their commitments the Authorities will carry out inspections, which will consist of a visit on board a ship in order to check the certificates and documents as referred to in section 2 of Annex 1. Furthermore the Authorities will satisfy themselves that the crew and the overall condition of the ship, including the engine room and accommodation and including hygienic conditions, meets generally accepted international rules and standards.
  - In the absence of valid certificates or documents or if there are clear grounds for believing that the condition of a ship or of its equipment, or its crew does not substantially meet the requirements of a relevant instrument, a more detailed inspection will be carried out, as referred to in section 5 of Annex 1. Examples of clear grounds are given in section 4 of Annex 1.
  - The Authorities will include control on compliance with on board operational requirements in their inspections.
- 3.2 The Authorities will ensure that an inspection in accordance with the provisions of section 3.1 is carried out on any ship not subject to expanded inspection with a target factor greater than 50 in the SIReNaC information system, provided that a period of at least one month has elapsed since the last inspection carried out in the region of the Memorandum.
- A ship in one of the categories in section 8.2 of Annex 1, is liable to an expanded inspection after a period of twelve months since the last expanded inspection carried out in a port within the region of the Memorandum.

#### Section 1 Priority inspections

- 1.1 Regardless of the value of the target factor, as referred to in Section 1.2, the following ships shall be considered as an overriding priority for inspection:
  - .1 Ships which have been reported by pilots or port authorities in accordance with section 1.5 of the Memorandum;
  - .2 Ships carrying dangerous or polluting goods, which have failed to report all relevant information concerning the ship's particulars, the ship's movements and concerning the dangerous or polluting goods being carried to the competent authority of the port and coastal State;
  - .3 Ships which have been the subject of a report or notification by another Authority:
  - .4 Ships which have been the subject of a report or complaint by the master, a crew member, or any person or organization with a legitimate interest in the safe operation of the ship, shipboard living and working conditions or the prevention of pollution, unless the Authority concerned deems the report or complaint to be manifestly unfounded; the identity of the person lodging the report or complaint must not be revealed to the master or the shipowner of the ship concerned;
  - .5 Shios which have been:
    - involved in a collision, grounding or stranding on their way to the port,
    - accused of an alleged violation of the provisions on discharge of harmful substances or effluents,
    - manoeuvred in an erratic or unsafe manner whereby routing measures, adopted by the IMO, or safe navigation practices and procedures have not been followed, or
    - otherwise operated in such a manner as to pose a danger to persons, property or the environment;
  - .6 Ships which have been suspended or withdrawn from their class for safety reasons in the course of the preceding 6 months.
  - .7 Ships which cannot be identified in the SIRcNaC information system.
- 1.2 In determining the order of priority for the inspection of ships, the Authority shall take into account the order indicated by the target factor displayed on the SIReNaC information system. The following elements are relevant for the targeting factor:
  - .I Ships visiting a port of a State, the Authority of which is a signatory to the Memorandum, for the first time or after an absence of 12 months or more. In the absence of appropriate data for this purpose, the Authorities will rely upon the available SIReNaC data and inspect those ships which have not been registered in the SIReNaC following the entry into force of that database on 1 January 1993;
  - Ships not inspected by any Authority within the previous 6 months;
  - .3 Ships whose staintory certificates on the ship's construction and equipment, issued in accordance with the Conventions, and the classification certificates, have been issued by an organization which is not recognized by the Authority;
  - .4 Ships flying the flag of a State appearing in the black-list as published in the annual report of the MOU

- Ships which have been permitted by the Authority to leave a port of its State on certain conditions:
  - a) deficiency to be rectified before departure
  - b) deficiency to be rectified at the next port
  - c) deficiencies to be rectified within 14 days
  - d) deficiencies for which other conditions have been specified.
  - e) if ship related action has been taken and all deficiencies have been rectified;
- Ships for which deficiencies have been recorded during a previous inspection, .6 according to the number of deficiencies;
- .7 Ships which have been detained in a previous port;
- Ships flying the flag of a non-Party to a relevant instrument; 8.
- 9. Ships with recognized organization deficiency ratio above average;
- .10 Ships in a category referred to in section 8 of this Annex;
- Other ships above 13 years old. .11

#### Section 2 Examination of certificates and documents

At the initial inspection the port State control officer will, as a minimum and to the extent applicable, examine the following documents:

- International Tonnage Certificate (1969); .1
- .2 Passenger Ship Safety Certificate;
- Cargo Ship Safety Construction Certificate;
- 4 Cargo Ship Safety Equipment Certificate;
- .5 Cargo Ship Safety Radio Certificate;
- Exemption Certificate and any list of cargoes (as per SOLAS II-2/53.1.3);
- .6 .7 .8 Cargo Ship Safety Certificate;
- Document of Compliance (SOLAS 74, Regulation II-2/54)
- 9 Dangerous goods special list or manifest, or detailed stowage plan;
- .10 International Certificate of Fitness for the Carriage of Liquefied Gases in Bulk, or the Certificate of Fitness for the Carriage of Liquefied Gases in Bulk, whichever is appropriate:
- .11. International Certificate of Fitness for the Carriage of Dangerous Chemicals in Bulk, or the Certificate of Fitness for the Carriage of Dangerous Chemicals in Bulk, whichever is appropriate;
- .12 International Oil Pollution Prevention Certificate;
- International Pollution Prevention Certificate for the Carriage of Noxious .13 Liquid Substances in Bulk;
- .14 International Load Line Certificate (1966);
- International Load Line Exemption Certificate; .15
- .16 Oil Record Book, parts I and II;
- .17 Shipboard Oil Pollution Emergency Plan
- .18 Cargo Record Book;
- .19 Minimum Safe Manning Document,
- .20 Certificates issued in accordance with STCW Convention;
- .21 Medical certificates (see ILO Convention No. 73);
- .22 Table of shipboard working arrangements (see ILO Convention No. 180 and STCW95)
- .23 Records of hours of work or rest of seafarers (see ILO Convention No. 180)
- .24 Stability information:
- .25 Copy of Document of Compliance and Safety Management Certificate issued in accordance with the International Management Code for the Safe Operation of Ships and for Pollution Prevention;

## Section 4 Examples of "clear grounds" for a more detailed inspection

In applying 3.1 of the Memorandum, "clear grounds" which warrant a more detailed inspection include the following:

- .1 the ship has been identified as a priority case for inspection, under section 1.1 and section 1.2.3, 1.2.4, 1.2.5b, 1.2.5.c, and 1.2.8 of this Annex;
- .2 during examination of the certificates and documents referred to in section 2 of this Annex, inaccuracies have been revealed or the documents have not been properly kept or updated;
- .3 indications that the relevant crew members are unable to communicate appropriately with each other, or with other persons on board, or that the ship is unable to communicate with the shore-based authorities either in a common language or in the language of those authorities;
- evidence of cargo and other operations not being conducted safely or in accordance with IMO guidelines;
- .5 failure of the master of an oil tanker to produce the record of the oil discharge monitoring and control system for the last ballast voyage;
- .6 absence of an up-to-date muster list, or crew members not aware of their duties in the event of fire or an order to abandon the ship;
- .7 the emission of false distress alerts not followed by proper cancellation procedures:
- .8 the absence of principal equipment or arrangements required by the conventions:
- .9 evidence from the port State control officer's general impressions and observations that serious hull or structural deterioration or deficiencies exist that may place at risk the structural, watertight or weather tight integrity of the ship;
- .10 excessively unsanitary conditions on board the ship;
- .11 information or evidence that the master or crew is not familiar with essential shipboard operations relating to the safety of ships or the prevention of pollution, or that such operations have not been carried out;
- .12 the absence of a table of shipboard working arrangements or records of hours of work or rest of seafarers (see ILO180).

#### Section 5 More detailed inspection

#### 5.1 General

- 5.1.1 In the absence of valid certificates or documents or after the establishment of clear grounds, the port State control officer will:
  - .1 conduct a more detailed inspection in the area(s) where clear grounds were established:
  - .2 carry out a more detailed inspection in other areas at random; and
  - .3 include further checking of compliance with on-board operational requirements.
- 5.1.2 In the exercise of a more detailed inspection the port State control officer will take into account:
  - the provisions of this section;
  - .2 the provisions of the International Maritime Dangerous Goods Code;
  - .3 the provisions of sections 6 and 7 of this Annex, as appropriate.

Recalling the Final Declaration adopted on 2 December 1980 by the Regional European Conference on Maritime Safety which underlined the need to increase maritime safety and the protection of the marine environment and the importance of improving living and working conditions on board ship;

Noting with appreciation the progress achieved in these fields by the International Maritime Organization and the International Labour Organization;

Noting also the contribution of the European Union towards meeting the above mentioned objectives;

Mindful that the principal responsibility for the effective application of standards laid down in international instruments rests upon the authorities of the State whose flag a ship is entitled to fly;

Recognizing nevertheless that effective action by port States is required to prevent the operation of substandard ships;

Recognizing also the need to avoid distorting competition between ports;

Convinced of the necessity, for these purposes, of an improved and harmonized system of port State control and of strengthening co-operation and the exchange of information;

have reached the following understanding:

#### Section 1 Commitments 1.1 Each Authority will give effect to the provisions of the present Memorandum and the Annexes thereto, which constitute an integral part of the Memorandum. 1.2 Each Authority will maintain an effective system of port State control with a view to ensuring that, without discrimination as to flag, foreign merchant ships calling at a port of its State, or anchored off such a port, comply with the standards laid down in the relevant instruments as defined in section 2. Each Authority may also carry out controls on ships at off-shore installations. 1.3 Each Authority will achieve an annual total of inspectious corresponding to 25% of the average number of individual foreign merchant ships, hereinafter referred to as 'ships'. which entered the ports of its State during the three last calendar years for which statistics are available. Each Authority will consult, cooperate and exchange information with the other 1,4 Authorities in order to further the aims of the Memorandum. Each Authority, or any other body, as the case may be, will establish an appropriate 1.5 procedure for pilot services and port authorities to immediately inform the competent Authority of the port State, whenever they learn in the course of their normal duties that there are deficiencies which may prejudice the safety of the ship, or which may pose a threat of harm to the marine environment.

#### Section 2 Relevant instruments

- 2.1 For the purposes of the Memorandum 'relevant instruments' are the following instruments:
  - .1 the International Convention on Load Lines, 1966 (LOAD LINES 66);
  - .2 the Protocol of 1988 relating to the International Convention on Load Lines, 1966 (LL PROT 88);
  - .3 the International Convention for the Safety of Life at Sea, 1974 (SOLAS 74);
  - .4 the Protocol of 1978 relating to the International Convention for the Safety of Life at Sea, 1974 (SOLAS PROT 78);

- .6 the International Convention for the Prevention of Pollution from Ships, 1973, as modified by the Protocols of 1978 and 1997 relating thereto (MARPOL 73/78);
- .7 the International Convention on Standards of Training, Certification and Watchkeeping for Seafarers, 1978 (STCW 78);
- .8 the Convention on the International Regulations for Preventing Collisions at Sea, 1972 (COUREG 72);
- the International Convention on Tonnage Measurement of Ships, 1969 (TONNAGE 69);
- .10 the Merchant Shipping (Minimum Standards) Convention, 1976 (ILO Convention No. 147) (ILO 147);
- .11 the Protocol of 1996 to the Merchant Shipping (Minimum Standards) Convention, 1976 (ILO Convention No. 147) (ILO147 PROT 96);

'Inspection of Labour Conditions on board Ship: Guide-lines for procedure".

- the International Convention on Civil Liability for Oil Pollution Damage, 1992. With respect to ILO 147 and the ILO Protocol 1996, each Authority will apply the procedures referred to in section 7 of Annex 1 for the application of ILO publication
- 2.3 Each Authority will apply those relevant instruments which are in force and to which its State is a Party. In the case of amendments to a relevant instrument each Authority will apply those amendments which are in force and which its State has accepted. An instrument so amended will then be deemed to be the 'relevant instrument' for that Authority.
- 2.4 In applying a relevant instrument, the Authorities will ensure that no more favourable treatment is given to ships of non-Parties or to ships below convention size. The Authorities will thereby apply the procedures specified in section 3 of Annex 1.

#### Section 3 Inspection Procedures, Rectification and Detention

2.2

3.1 In fulfilling their commitments the Authorities will carry out inspections, which will consist of a visit on board a ship in order to check the certificates and documents as referred to in section 2 of Annex 1. Furthermore the Authorities will satisfy themselves that the crew and the overall condition of the ship, including the engine room and accommodation and including hygicnic conditions, meets generally accepted international rules and standards.

In the absence of valid certificates or documents or if there are clear grounds for believing that the condition of a ship or of its equipment, or its crew does not substantially meet the requirements of a relevant instrument, a more detailed inspection will be carried out, as referred to in section 5 of Annex 1. Examples of clear grounds are given in section 4 of Annex 1.

The Authorities will include control on compliance with on board operational requirements in their inspections,

- 3.2 The Authorities will ensure that an inspection in accordance with the provisions of section 3.1 is carried out on any ship not subject to expanded inspection with a target factor greater than 50 in the SIReNaC information system, provided that a period of at least one month has clapsed since the last inspection carried out in the region of the Memorandum.
- A ship in one of the categories in section 8.2 of Annex 1, is liable to an expanded inspection after a period of twelve months since the last expanded inspection carried out in a port within the region of the Memorandum.